

## PROFIBUS®-DP Bus Tees



### RKSX 2RSSW 45

fully shielded *eurofast*® tee

PROFIBUS-DP tee (12 M baud), M 12x1

Dimensions	Pin Configuration	Wiring diagram
<p>2.76 [70.0] 1.68 [40.2] 1.33 [33.8] .91 [23.0] 1.81 [40.8] 1.16 [29.3] .75 [19.0]</p>	<p><i>eurofast</i>® male      <i>eurofast</i>® female</p>	

### RKSX 2RSSW 45-0001

fully shielded *eurofast*® tee

PROFIBUS-DP tee (12 M baud), M 12x1

<p>2.76 [70.0] 1.68 [40.2] 1.33 [33.8] .91 [23.0] 1.81 [40.8] 1.16 [29.3] .75 [19.0]</p>	<p><i>eurofast</i>® male      <i>eurofast</i>® female</p>	
--	---	--

Note: This part must be used when joining two tees together directly. A female terminating resistor will not work with this tee since there is no ground and power connection on the male side.

4



## PROFIBUS-DP Bus Y-junction

### VB2/FSW/FKW/FSW 45

fully shielded *eurofast*®

PROFIBUS tee (12MBd), M12x1

Dimensions	Pin configuration	Wiring diagram
<p>2.39 [60.8] REF .91 [23.0] .51 [13.0] M12x1 M12x1 M12x1 M12x1 .58 [25.0] .18 [4.5] .32 [8.0]</p>	<p><i>eurofast</i>® male      <i>eurofast</i>® female</p>	